

WPR26LA042

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Airport Operations)



Photograph 2 - View of bent and severed engine mount attached to nose gear (Courtesy of Pilot)