

WPR26LA057

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Carbon Fiber Abrasion right of nose-gear (courtesy of airport operations director)



Photograph 2 - Carbon Fiber Abrasion right of nose-gear (courtesy of airport operations director)



Photograph 3 - Carbon Fiber Abrasion on belly (courtesy of airport operations director)



Photograph 4 - Carbon Fiber Abrasion on belly (courtesy of airport operations director)



Photograph 6 - Carbon Fiber Abrasion on belly (courtesy of airport operations director)



Photograph 7 - Aircraft on Runway 27 (courtesy of airport operations director)