

WPR26LA081

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aft fuselage damage (Courtesy of local law enforcement)



Photograph 2 - View of vertical stabilizer / rudder damage (Courtesy of local law enforcement)