

WPR26LA092

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of aircraft from the front, post recovery (courtesy of FAA)



Photograph 2 - Left-wing leading-edge damage (courtesy of FAA)



Photograph 3 - Left-wing leading-edge damage (courtesy of FAA)



Photograph 4 - Right-wing leading-edge damage (courtesy of FAA)



Photograph 5 - Right-wing leading-edge damage (courtesy of FAA)