

WPR26LA099

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Side view of tailboom damage (Courtesy of Aircraft Operator)



Photograph 2 - Bottom view of tailboom damage (Courtesy of Aircraft Operator)



Photograph 3 - Rear view of tailboom damage (Courtesy of Aircraft Operator)



Photograph 4- View of tailboom, tail rotor, and light post damage (Courtesy of Pilot)