


WPR26LA104

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the left main landing gear attachment points (Courtesy of LEA)



Photograph 2 - View of the left main landing gear attachment point separation (Courtesy of LEA)