

WPR26LA113

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplanes right side on runway (Courtesy of airport operations)



Photograph 2 - View of nose gear buckled (Courtesy of airport operations)



Photograph 3 - View of firewall and fuselage damage (Courtesy of operator)



Photograph 4 - View of damage to the right-side floorboard (Courtesy of operator)



Photograph 5 - View of damage to left side floorboard (Courtesy of operator)