

WPR26LA122

INVESTIGATION PHOTOGRAPHS



Photograph 1 - The Cessna 182, with substantial damage visible to the empennage and right wing, inverted near taxiway A6. (Courtesy of airport operations).



Photograph 2 - The Cessna 182 with the SkyWest CRJ700 visible on the left. (Courtesy of airport operations).



Photograph 3 - The CRJ700 on the commercial ramp. (Courtesy of airport operations).



Photograph 4 - An annotated diagram depicting the commercial ramp at FLG.