

WPR26LA143

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane at accident scene (Courtesy of airfield operations)



Photograph 2 - Right side view of airplane showing missing landing gear (Courtesy of airfield operations)



Photograph 3 - View of damage to right strut (Courtesy of airfield operations)



Photograph 4 - View of damage to landing gear attachment point (Courtesy of airfield operations)