

WPR26LA156

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of bent struts. (Courtesy of Pilot)



Photograph 2 - View of rudder damage. (Courtesy of Pilot)