

WPR26LA192

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward view of airplane (Courtesy of airport ops)



Photograph 2 - Top view of broken wing root (Courtesy of insurance company)



Photograph 3 - Underside view of broken wing root (Courtesy of insurance company)