

WPR26LA193

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right wing lift strut (Courtesy of first responders)



Photograph 2 - View of rudder damage (Courtesy of first responders)