

WPR26LA199

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of helicopter at accident scene (Courtesy of airfield operations).



Photograph 2 - View of tail rotor and tailboom damage.



Photograph 3 - View of separated main rotor system (Courtesy of airfield operations).



Photograph 4 - View of mast separation point.