

WPR26LA203

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of top left wing broken tape. (Courtesy of Pilot)



Photograph 2 - View of spar root box crack. (Courtesy of Pilot)



Photograph 3 - View of puncture under right wing. (Courtesy of Pilot)