

WPR26LA208

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane (Courtesy of Airport Operations)



Photograph 2 - View of accident airplane (Courtesy of Airport Operations)



Photograph 3 - View of left wing lift strut damage (Courtesy of Airport Operations)



Photograph 4 - View of right main landing gear tire wear marks (Courtesy of Airport Operations)



Photograph 5 - View of left main landing gear tire wear marks (Courtesy of Airport Operations)