PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model B2D34C214-B

Propeller S/N 922202

Blade Design G90DHB-16E

Blade S/N's

No. 1 GE 184

No. 2 GE380

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High Feather 33.0

Start Lock _____

Low 13.9

Reverse /

Aircraft Manufacturer Mooney

Aircraft Model M20J

S/N 24-0053

Registration N201HH

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5/12/20	N201HH	TACH **4787.92** TTPSMOH **0.0** Installed overhauled propeller on and torqued to 60 foot pounds per the placard attached to the propeller. Installed and rigged overhauled propeller governor per the Mooney Service manual. Post maintenance ground run and leak checks satisfactory. Aircraft approved for return to service. Bertrand V Lewis [redacted] A&P [redacted]	