



RECORD OF CONVERSATION

Noreen Price
Aviation Accident Investigator
Alaska Regional Office

Date: July 12, 2016 @ 1500
Person Contacted: Kyler Hylton, King Salmon Airport Manager
NTSB Accident Number: ANC16CA036, N3969Q

Narrative:

Mr. Hylton called me after I sent an email request for reported wind conditions at King Salmon airport at the time of the accident. Mr. Hylton referred to his accident notes and said that the winds at the time of the accident were from 070 degrees at 12 knots gusting to 22 knots.

At the conclusion of our conversation, Mr. Hylton remarked that the winds at King Salmon airport are often “squirrely” and can be challenging at times.