



Photo 1 - PZL-104, N9726N at Talkeetna Airport



Photo 2 – Left wing and aileron damage



Photo 3 – Left lower fuselage damage