



Photo 1 – N88452 Bellanca Citabria 7GCBC wreckage



Photo 2 - Fractured tree top



Photo 3 - Red paint transfer on broken tree section



Photo 4 - Front view of airplane at the accident scene



Photo 5 - Detailed examination in a hangar



Photo 6 - Right wing root damage



Photo 7 - Left wing with vortex generators



Photo 8 - Lycoming O-320 engine with right side damage



Photo 9 - Left side pilot seat leg fractures and modified bracket