



RECORD OF CONVERSATION

Michael J. Hodges
Air Safety Investigator
Alaska Regional Office
Office of Aviation Safety
National Transportation Safety Board

Date: 06/27/2017
Person Contacted: Spencer Leonard (FAA Aviation Safety Inspector)
NTSB Case Number: ANC17LA033

Narrative:

The following is a synopsis of the information provided by Spencer Leonard to the NTSB IIC, via an email message.

- The pilot, Kenneth Jones, did not have an external load permit (FAA Form 8310-7 Special Airworthiness Certificate) on file with the FAA for N4018H.
- The pilot did have an external load permit on file for the Cessna A185F he previously had. The external load permit for the Cessna A185F had been on file with the FAA since 2003.
- The pilot reported he had been doing external load operations with N4018H for a while.