

Probable Cause Correction ANC17LA053

The pilot's improper decision to takeoff in an area of rough water and ocean swells, which resulted in a failure of the right float struts.

Deleted: wing lift