



Photo 1 – Todd's Strip Airport 5AK5



Photo 2 - Airplane tire track in ditch



Photo 3 - N5392Y Piper PA-18 inverted in ditch



Photo 4 - Damaged left wing lift strut