

ANC18LA002

October 11, 2017

Ocean Springs, MS

N7566D

Video 2 – Engine Run with Servicable PTO Ignition Coil

Contact the Records Management Division for copies:

National Transportation Safety Board

Records Management Division

490 L'Enfant Plaza East, SW

Washington, DC 20594

202-314-6551

800-877-6799

pubinq@ntsb.gov