

From: [REDACTED]
To: [REDACTED]
Cc: [REDACTED]
Subject: RE: N363JH Accident - Update
Date: Thursday, February 1, 2018 15:25:43

Hi Mike

After the internal inspection the damaged engines where not economically feasible to repair. It was cheaper to purchase new engines for N363JH.

Best Regards,

Ben Koelsch
Bering Air Inc.
[REDACTED]

From: Hodges Michael [REDACTED]
Sent: Thursday, February 01, 2018 1:12 PM
To: [REDACTED]
Cc: [REDACTED]
Subject: N363JH Accident - Update

Hi Ben,

Just following up with the accident involving N363JH (NTSB accident number ANC18LA005).

Just wanted to make sure my notes are correct – have you heard any word back on the two engines with regards to any damage sustained to the internal components?

Thank you.

Mike

Mike J. Hodges
Aviation Accident Investigator
Alaska Regional Office
Office of Aviation Safety
National Transportation Safety Board

222 West 7th Avenue
Room 216, Box 11
Anchorage, AK 99513-7500 USA

Cellular: [REDACTED]
Facsimile: [REDACTED]

Response Operations Center (24/7): 1-844-373-9922

Email: [REDACTED]

Internet: <http://www.nts.gov/air>

“From tragedy we draw knowledge to improve the safety of us all.”

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.