



RECORD OF CONVERSATION

Noreen Price
Aviation Accident Investigator
Alaska Regional Office

Date: June 29, 2017
Persons Contacted: Aaron Pomeroy, pilot rated passenger
NTSB Accident Number: ANC18LA051, N7675D

Narrative:

Mr. Pomeroy was the front seat passenger during the accident of the PA-18 at lake Hood Seaplane Base on June 29, 2018. He was interviewed at the scene of the accident. The following is a summary of the interview:

- Mr. Pomeroy is a commercial rated multiengine land pilot and single engine land and sea rated private pilot. He was in the front seat of the PA-18 and he was not flying.
 - He is married to the owner's granddaughter.
 - He assisted the owner/PIC in fueling the airplane at the slip.
 - The takeoff was performed by the PIC from the back seat and appeared normal. At a couple hundred ft, the engine quit. The PIC pushed the nose over and asked if the fuel was on, which it was. The PIC was pumping the throttle and Mr. Pomeroy thought the engine was surging and maybe coming back. He remembers impacting the ground in a nose down attitude and then banking right. After the airplane stopped, he was able to egress through the door on his own, and then the fire department assisted the PIC.
- The end.*