



**Photo 1 – N1526A PA-20 exhibiting substantial damage to the left wing and horizontal stabilizer. (Photograph courtesy of the Federal Aviation Administration.)**