



RE: N354PA-Accident Fort Greely, AK-AS350



9/15/2020




Eric,

I was not able to find any definitive reason for the departure of the door. Two witnesses confirm it was closed prior to takeoff. This ones a bit of a mystery of way a sliding door opened in flight and departed the aircraft. The door hinges all looked good minus the two places that you can see the door slides ripped out of. Nothing further to add. Let me know if I missed something.

Thanks

RE: N354PA-Accident Fort Greely, AK-AS350




9/15/2020

 You replied to this message on 9/15/2020 10:57 AM.

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

The rollers were gone, just a partial slide piece on the lower rail was present.

RE: N354PA-Accident Fort Greely, AK-AS350



9/21/2020

 You replied to this message on 9/22/2020 7:34 AM.

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Eric,

Sorry no, I sent you everything I took. There was no other damage to any other part of the helicopter, just FYI.