



NTSB RECORD

NTSB Accident Number: ANC21LA056

Narrative:

The following is a summary of the Alaska State Troopers report from the accident:

- The pilot stated that he was not sure what had happened during takeoff. He believes that wind shifted, and he lost lift at the end of the runway. The pilot did not provide any further information.