

NATIONAL TRANSPORTATION SAFETY BOARD • PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT
REPORT Use this form (Form 6120.1) to report civil and public aircraft accidents and incidents**BASIC INFORMATION****Accident/Incident Location**Nearest City/Place: Pig Lake State: AKZIP: 99652 Country: USALatitude: N 61.4455 Longitude: W 150.9137

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/TimeDate: 07/15/2024 Local Time: 1300
mm/dd/yyyyTime Zone: AKSTCollision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None**AIRCRAFT INFORMATION**Registration Number: N2466HManufacturer: PiperModel: PA-18-150Serial Number: 18-7909187Year of Manufacture: 1979Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Original Design ☐ Kit/Plans

Make: _____

- ☐
- IFR-Equipped and Certified
-
- ☐
- Commercial Space Flight
-
- ☐
- Unmanned Aircraft

Maximum Gross Weight: 2000 lbs.Weight at Time of Accident/Incident: 1550 lbs.Number of Seats: 2 Flight Crew Seats: 1Cabin Crew Seats: 1 Passenger Seats: 1Number of Engines: 1**Category of Aircraft**
(Select one)

- ☒
- Airplane
-
- ☐
- Balloon
-
- ☐
- Blimp/Dirigible
-
- ☐
- Glider
-
- ☐
- Gyroplane
-
- ☐
- Helicopter
-
- ☐
- Powered Lift
-
- ☐
- Rocket
-
- ☐
- Ultralight
-
- ☐
- Unknown

Type of Airworthiness Certificate
(Check all that apply)**Standard**

- ☒
- Normal
-
- ☐
- Aerobatic
-
- ☐
- Balloon
-
- ☐
- Commuter
-
- ☐
- Transport
-
- ☐
- Utility

Special

- ☐
- Restricted
-
- ☐
- Limited
-
- ☐
- Provisional
-
- ☐
- Special Flight
-
- ☐
- Experimental
-
- ☐
- Special Light-Sport
-
- ☐
- Experimental Light-Sport

- ☐
- Certificate of Authorization or Waiver (COA)
-
- ☐
- None
- ☐
- Unknown

Landing Gear

(Check all that apply)

- ☐
- Retractable
-
- ☐
- Tricycle
-
- ☒
- Tailwheel
-
- ☐
- Emergency Float
-
- ☐
- Float
-
- ☐
- Amphibian
-
- ☐
- Other Launch/Recovery System
-
- ☐
- None

- ☐
- High Skid
-
- ☐
- Skid
-
- ☐
- Ski/Wheel
-
- ☐
- Hull
-
- ☐
- Ski
-
- ☐
- Unknown

Engine Type (Select one)

- ☒
- Reciprocating
-
- ☐
- Turbo Shaft
-
- ☐
- Turbo Prop
-
- ☐
- Turbo Jet
-
- ☐
- Turbo Fan
-
- ☐
- Electric
-
- ☐
- Liquid Rocket
-
- ☐
- Solid Rocket
-
- ☐
- Hybrid Rocket
-
- ☐
- None
-
- ☐
- Unknown

Fuel System Type (Reciprocating)

- ☐
- Carburetor
- ☐
- Fuel Injected

Engine	Engine Manufacturer	Engine Model/Series	Engine Serial Number	Date of Mfg. (mm/dd/yyyy)	Rated Power ☒ Horsepower or ☐ Lbs. of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>Lycoming</u>	<u>O-320-B2D</u>			<u>160</u>	<u>450</u>		<u>450</u>
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐
- 100-Hour
-
- ☐
- AAIP
-
- ☒
- Annual
-
- ☐
- Continuous Airworthiness
-
- ☐
- Condition Inspection
-
- ☐
- Unknown

Date of Last Inspection: 12/23/2023
mm/dd/yyyyAirframe Total Time: 2500 hrs

Hours measured at (Select one)

☒ Last Inspection ☐ Time of Accident/Incident**Type of Maintenance Program (Select One)**

- ☐
- Annual
-
- ☐
- Conditional (Amateur-built only)
-
- ☐
- Manufacturer's Inspection Program
-
- ☐
- Other Approved Inspection Program
-
- ☐
- (AAIP) Continuous Airworthiness
-
- ☐
- Other, specify: _____

Description of Fire Extinguishing System

- ☐
- None
-
- ☐
- Specify: _____

Additional Equipment

- ☐
- ADS-B
-
- ☐
- Airframe Parachute
-
- ☐
- Angle of Attack Indicator
-
- ☐
- Autopilot
-
- ☐
- Autopilot/FMS, Model: _____
-
- ☐
- Coupled Flight Director
-
- ☐
- Data Recorder
-
- ☐
- Device Stall Warning System
-
- ☒
- Electronic Flight Bag or Handheld Device
-
- ☐
- Electronic Multifunction Display
-
- ☒
- Electronic Primary Flight Display
-
- ☐
- Flight Management System

- ☐
- Handheld GPS
-
- ☐
- Heads Up Display
-
- ☐
- Night Vision Goggles
-
- ☐
- Onboard Weather
-
- ☐
- Primary Flight Display
-
- ☐
- SAS, Axis (circle one) 2, 3, 4, Model: _____
-
- ☐
- Satellite Tracking Device
-
- ☐
- Stall Warning System
-
- ☐
- Video Recording Device
-
- ☐
- Wire Strike Detection
-
- ☐
- Wire Strike Protection
-
- ☐
- Other, Specify: _____

ELT Installed: ☒ Yes ☐ No If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)Was ELT still mounted in aircraft? ☒ Yes ☐ NoWas ELT still connected to antenna? ☒ Yes ☐ NoDid ELT activate? ☐ Yes ☒ NoIf activated: Did ELT aid in locating aircraft? ☐ Yes ☒ NoIf not activated: Indicate Reason: ☐ Impact Damage☐ Fire Damage ☐ Battery ☐ Expired Damaged ☒ UnknownPropeller 1 ☒ Fixed Pitch

- ☐
- Controllable Pitch
-
- ☐
- Ground Adjustable

Manufacturer: McClellanModel: Pacer

Propeller 2

- ☐
- Fixed Pitch
-
- ☐
- Controllable Pitch
-
- ☐
- Ground Adjustable

Manufacturer: _____

Model: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Raven Girl LLCCity: Eagle RiverState: AKZIP: 99577 Country: USA

Fractional Ownership Aircraft:

☐ Yes☒ No**Operator of Aircraft**☐ The Operator is also the Registered Owner☐ Same address as Registered OwnerName: Torsten Renner

Doing Business As: _____

City: Eagle RiverState: AK

Air Carrier/Operator Designator (4-character code): _____

ZIP: 99577 Country: USA**Operating Certificates Held**

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
 Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
☐ FAR 450
☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
☐ Public Aircraft (Select one)
 ☐ Armed Forces
 ☐ Federal
 ☐ State
 ☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry ☐ Unknown

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)

Airport Name: _____

Airport Identifier: _____

Proximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/A

Distance From Airport Center: _____ sm.

Direction From Airport: _____ degrees true

Airport Elevation: _____ ft. MSL

Runway Information

Runway ID: _____ Length: _____ ft. Width: _____ ft.

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Ice ☐ Snow
☐ Concrete ☐ Gravel ☐ Macadam ☐ Water
☐ Dirt ☐ Helideck ☐ Metal/Wood ☐ Unknown
☐ Elevated Heliport ☐ Helistop ☐ Off-site landing area

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR ☐ Unknown
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling

VFR Approach (Check all that apply)

- ☐ None
☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION**"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident**

☐ Captain ☐ First Officer ☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" IdentificationFirst Name: TorstenCity of Residence: Engle RiverMiddle Initial: E.State: AKZIP: 99579Last Name: RennerCountry: USAAge at time of Accident/Incident: 24Date of Birth: [REDACTED] (mm/dd/yyyy)

Certificate Number: _____

Degree of Injury

☒ None ☐ Serious
☐ Unknown ☐ Fatal
☐ Minor

Seat Occupied

☐ Left ☒ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☐ 3-point
☒ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☒ Commercial
☐ US Military ☐ Private ☐ Recreational
☐ Airline Transport ☐ Foreign ☐ Sport
☐ Student ☐ Flight Engineer

☐ Supplemental Restraint type: _____

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☒ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☒ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

01/17/2024
 mm/dd/yyyy

Medical Certificate Limitations**Medical Certificate Special Limitations****Personal Flight Equipment** (Check all that apply)

☐ Fire resistant flight suit ☒ Helmet ☐ Laser protective visor/glasses ☒ Personal locator beacon(s) (PLB) ☐ Fire resistant gloves
☒ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

05/30/2024
 mm/dd/yyyy

Flight Review Aircraft

Make: Beechcraft
 Model: BE-1700-C

Airplane Rating(s)

(Check all that apply)

☒ Single-Engine Land
☒ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)

☐ None
☒ Airplane Single-Engine
☐ Airplane Multiengine
☐ Gyroplane
☐ Powered lift

☒ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings and Applicable Logbook Endorsements

Tailwheel endorsement

Student Endorsements (Include dates)

Flight Time (Enter hours for each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Multi-engine Rotorcraft	Tail-wheel
						Actual	Simulated					
Total Time	939.3	335	672.7	266.6	39.7	177.3	47.9					335
Pilot in Command (PIC)	547	332	600	-	30	-	-					332
Time as Instructor	4.0	0	4.0	-								
This Make/Model												
Last 90 Days	250	20	50	200								
Last 30 Days	160	10	30	120								
Last 24 Hours												

First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown ☐ Supplemental. Restraint type: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown ☐ Supplemental. Restraint type: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ Zip: _____ Last name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other Personal Flight Equipment (Check all that apply) ☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ PLB ☐ Fire resistant gloves ☐ Night vision goggles ☐ Helmet visor ☐ Personal flotation ☐ Other: _____	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown ☐ Supplemental. Restraint type: _____	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If under 5 years, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>PAQY</u> City: <u>Girdwood</u> State: <u>AK</u> Country: <u>USA</u>	Time of Departure Time: <u>11:30</u> Time Zone: <u>AKST</u>	Flight Information Flight Number: _____ Operating as Flight _____	Destination Airport ID: <u>PAQY</u> City: <u>Girdwood</u> State: <u>AK</u> Country: <u>USA</u>	Type Flight Plan Filed ☐ None ☐ Company VFR ☐ Military VFR ☐ VFR ☐ VFR/IFR ☐ IFR ☐ Unknown Activated? ☐ Yes ☐ No ☐ Unknown
--	--	--	---	--

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None
☐ Minor
☒ Substantial
☐ Destroyed
☐ Unknown

Aircraft Fire

- ☒ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Fire at Unknown Time
☐ Unknown

Aircraft Explosion

- ☒ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Fire at Unknown Time
☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet, if necessary.)*

Left wing lift struts were bent as wing touched the ground. Prop strike bent the blades back. Skylight was busted out of its secure spot, and the tail feather fabric was loosed up, but not torn, from impact with soft ground as the aircraft flipped. No damage to other property.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink.)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Departure Time: ~1130am from Girdwood Airport PAQY

Intended destination: Coal Creek valley basin, then back to Girdwood as final.

Mission: Scout for potential gold mining areas up the Coal Creek drainage.

Weather: Bright, blue sky, ~45-55 degrees F, consistent wind from the South.

No services obtained.

After leaving Girdwood, I climbed to 3000ft and proceeded to fly west towards the class C. I got the PANC Atis and contacted approach on 126.4 to secure clearance through the airspace. After being cleared through the Merrill Delta, and crossing the approach course for 15 into ANC, I descended to 1500 and proceeded West along the powerlines.

As I got closer to Little Mt Susitna, I climbed up to around 2500 ft and over flew the larger strip on the top of the mountain, adjacent to the weather station/ structure. After doing a low approach and visual inspection of that field, I proceeded to do 5 full stop landings with backtaxi to the north end of the strip each time. The ground was rocky with sparse vegetation. Some moisture was present, but no standing water on or around the field. With winds around 10kts gusting to 20kts, I made sure to keep proper control deflections in during taxi, diving away from the wind. After those landings, I proceeded east down the mountain to a more challenging strip that I knew of, that was more in line with the wind.

After doing the same overfly procedure, I conducted 2 landings, with backtaxi to the north end of that strip, all with proper control inputs for the conditions. This field was similar to the one up the mountain, although less used. Slightly more low growing moss and small plants, and a bit more moisture as a result. My third landing was uneventful, but as I went to turn the aircraft to taxi back, I inputted forward stick, as well as power to turn the plane around. This lifted the tail feathers in the turn. As a result, the tail feathers caught a gust of wind, gently lifting the tail up, striking the prop, and leaving the aircraft to rest on its nose and left wings leading edge. The aircraft rested in that position for several seconds, before a gust caught the surfaces again, pushing the entire aircraft onto its back.

Unharmed, I exited the aircraft calmly, grabbed my survival bags, and sent my location via Garmin inreach to my father, Mark Renner.

Shortly after I exited the aircraft, a tandem seat Piper aircraft on floats, that I recognized as Trail Ridge Air, overflowed over me several times. I got back into the aircraft, put on my helmet, turned on the master switch and attempted to make contact, however the radio antenna was buried in the ground. I could hear the pilot in the air ask if I could hear him, but I was unable to reply. Trail Ridge contacted the RCC, followed shortly by my father. I also activated my SOS function on my inreach and was able to talk live to a representative who was able to assist in giving rescuers my exact location. Within 2 hours I was in the chopper eastbound.

OPERATOR/OWNER SAFETY RECOMMENDATION *(How could this accident/incident have been prevented?)*

This accident occurred on the first day I had had off work in over 2 weeks. It was also a beautiful day weather wise to go fly. These external pressures made me overlook the potential risks associated with doing offfield work in a light aircraft on a windier than average day. Had I reflected on the conditions that were present, or perhaps chose a better area more shaded from wind to practice off field landings, this incident may have been prevented all together.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on a separate sheet.)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No
 (If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/ Cycles On Part

_____ Hours

_____ Cycles

Time Since This Part Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff
 (Convert from pounds, as necessary)

_____ 30 _____ Gallons

Fuel Type

☒ 100 Low Lead
☐ Automotive

☐ Jet A
☐ Jet A-1

☐ Unleaded AV
☐ Other, specify _____

Other Services, if any, prior to departure:

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location:

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft.)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft:

☐ Destroyed
☐ Substantial

☐ Minor
☐ None

Registered Owner of Other Aircraft

Pilot of Other Aircraft

Name: _____

Name: _____

City: _____

City: _____

State: _____ ZIP: _____

State: _____ ZIP: _____

Country: _____

Country: _____

ADDITIONAL INFORMATION (Additional space for answers to any question.)

By signing this form, I am consenting to the public release of the information provided herein.

Date of this report:

09/27/2024
mm/dd/yyyy

Name of Pilot/Operator:

Torsten Renner

Signature:

[Redacted Signature]

-or- ☐ Check here to electronically sign this document

If a person other than Pilot/Operator is filing this report

Name:

Title:

Signature:

-or- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

ANC24LA099

Reviewed by NTSB AS Division

Anchorage, AK

Name of Investigator

M. Rasmussen

Date Report Received

10/05/2024