

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Cantwell State: Alaska

ZIP: 99729 Country: United States

Latitude: 63.33 deg N Longitude: 149.13 deg West

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 03/10/2025 Local Time: 1200pm
mm/dd/yyyy

Time Zone: AKDT

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N5375R

Manufacturer: Cessna

Model: 172M

Serial Number: 17263527

Year of Manufacture: 1974

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 2550 lbs

Weight at Time of Accident/Incident: 2085 lbs

Number of Seats: 4 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 3

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☒ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Serial	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Penn Yann Aero	O-360-A4M	L-43497-27A	03/18/2022	180	6069.6	31	467
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☒ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: 01/02/2025
mm/dd/yyyy

Airframe Total Time: 10562.4 hrs

hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Sensenich

Model: 76EM8SPY-0-60

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ACK Technologies

Model or Part No.: E-04

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☒ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Arctic Flying ClubCity: FairbanksFractional Ownership Aircraft: ☐ Yes ☐ NoState: Alaska ZIP: 99708Country: United States**Operator of Aircraft**☒ Same As Registered Owner☐ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☐ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local

☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: SummitDistance From Airport Center: .25 smAirport Identifier: PASTDirection From Airport: 030 degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 2409 ft. msl**Runway Information**Runway ID: 21 (L/R/C) Length: 3814 ft Width: 80 ft**Runway/Landing Surface** (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☒ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☒ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☒ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☒ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☒ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling

☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing

☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Dawson City of Residence: Fairbanks
 Middle Initial: J State: Alaska ZIP: 99709
 Last Name: Lewandoski Country: United States
 Age at time of Accident/Incident: 31 Date of Birth: mm/dd/yyyy
 Certificate Number: mm/dd/yyyy

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☒ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown
Used
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☒ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☒ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☒ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

08/09/2023
 mm/dd/yyyy

Medical Certificate Limitations

Must use corrective lenses to meet vision standards at all required distances

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

04/18/2023
 mm/dd/yyyy

Flight Review Aircraft

Make: Piper

Model: PA-28R

Airplane Rating(s)

(Check all that apply)
☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☒ None
☐ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☐ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	434	322	434		39	8	57			
Pilot in Command (PIC)	370	260	370		35	8	55			
Time as Instructor										
This Make/Model					23	2	46			
Last 90 Days	21	21	21		1	0	1			
Last 30 Days	14	14	14				1			
Last 24 Hours	2	2	2							

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	0	0	0	0	0	0	0	0	0	0
Pilot in Command (PIC)	0	0	0	0	0	0	0	0	0	0
Time as Instructor	0	0	0	0	0	0	0	0	0	0
This Make/Model					0	0	0			
Last 90 Days	0	0	0	0	0	0	0	0	0	0
Last 30 Days	0	0	0		0	0	0	0	0	0
Last 24 Hours	0	0	0	0	0	0	0	0	0	0

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: PAFA

City: Fairbanks

State: Alaska

Country: United States

Time of Departure

Time: 1100

Time Zone: AKDT

Destination

Airport ID: PATK

City: Talkeetna

State: Alaska

Country: United States

Type Flight Plan Filed

☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR
 Activated? ☐ Yes ☒ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☒ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

2409 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☒ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☐ On-Board Weather

Weather Observation Facility

Facility ID: _____

Observation Time: _____

Time Zone: _____

Distance from Accident Site: _____ nm

Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

_____ ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or _____ (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
 or _____ MB

Wind Direction

☒ Variable

-or-
Direction: _____ degrees true

Wind Speed

☒ Calm
☐ Light and Variable

-or-
Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility >10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount Type
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount Type
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply) Severity
☒ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

The nose had dug into the snow, and the bottom engine cowling was dented, though the exhaust for the engine appeared to be in the normal orientation relative to the engine. No damage to the spinner, and the propeller was still straight, though with many scratches on the forward facing part of one blade. The right wing suffered a kink along the entire chord length, just inside of where the right strut meets the wing. Elsewhere on right wing I observed warped metal panels on the bottom side of the wing, primarily near the leading edge. The left wing suffered minimal visual damage. The flaps were almost completely in the raised position, though if they had been jarred during the crash, or the switch inside the cockpit had inadvertently been selected in the 'up' position while the battery was still running after the crash, I couldn't determine. The elevators were free of the snow and were still movable. The ailerons were also still movable, and the yoke moved correctly. The portion of the rudder visible above the snow had no damage and was still straight. The landing gear was intact with +

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

I had planned a solo flight for Monday, March 10, from Fairbanks to Talkeetna and back, to take advantage of the excellent weather over the Alaska Range. I began preflighting the aircraft around 10:20. During the preflight, I noticed the oil level was low, so I added 1 quart stored in the aircraft, per the club SOP. The oil was also scheduled to be replaced after my flight by the maintenance officer of the club. No other items were noted on the preflight. Afterward, I loaded the aircraft with two 8 gallon fuel bladders in the cargo area behind the rear passenger seat, the airplane engine blanket and personal survival equipment in the rear passenger seat, and my flight bag in the front passenger seat. Using Foreflight, I calculated my weight and balance, with a TOW of 2151 lbs, and a CG of 42 inches. With full fuel tanks I had more than enough fuel in the tanks for a flight to Talkeetna and back, but on long flights I liked to carry extra fuel in the bladders.

I did a final check of the weather along my route, also using Foreflight. I had already checked the weather using Foreflight the night before, and in the morning, so this was merely a final check that nothing along my route had changed dramatically. I was using my iPad running Foreflight, and a personal ADSB-In receiver which I use for airborne traffic alerts and to obtain in-flight weather information.

After getting the ATIS at Fairbanks, I was cleared to taxi from the East Ramp to 2R via Charlie. The runup proceeded normally, and I waited in the holding area at the end of taxiway Charlie for a few minutes extra to let the engine warm up a little bit more, as it had been a chilly morning. Takeoff was at approximately 11:00, and I was given a left hand turn on own navigation by departure, to avoid traffic to the southeast.

I gave ATC a heading of 212° for my initial heading, and leveled off at 3500' when departing the Class Delta. I held that course and altitude until I exited the TRSA. About 10 minutes after leaving the TRSA I turned to a heading of 193°, in order to 'cut the corner' of the Rex Dome and pass to the east of the dome in order to pick up the Parks Highway near Healy, instead of near Clear. As I approached the hills I gradually increased altitude to approximately 4000' to avoid some of the ridges between Rex Dome and Jumbo Dome. Around 11:40, I picked up the Parks Highway just south of the Healy airstrip (PAHV), and turned south to follow it, descending back down to around 2800'.

I made one radio call on the Healy River CTAF as I passed the airstrip, and one more as I passed over the McKinley Park airstrip (PAIN), to no response. Using my ADSB I saw there was no traffic indicated, but I knew that non-ADSB or transponder equipped aircraft frequently fly at low level through the passes, so I maintained my visual scan of the pass ahead of me. I left the CTAF for the area on Radio 1, and I also tried to pick up the PAIN AWOS on 135.75 on Radio 2, but heard nothing. This meant I was still on the Fairbanks altimeter setting throughout the flight. I had planned on picking up the Talkeetna altimeter as far out as I could.

I passed through Windy gap with a slight descent to perhaps 1000' or 1200' AGL, monitoring the CTAF for traffic announcements. Between Cantwell airport (PATW) and Summit airport (PAST), I noticed a double length semi-truck had run off into the ditch in the northbound lane of the Parks Highway. I quickly did a left-handed 180 to investigate and take pictures. As I came on to my original heading, roughly parallel to the highway southbound, I saw Summit airport just off my nose.

I had driven by Summit many times while on the highway, and had inquired about it from other pilots as an airstrip to base flying adventures in and around the mountains, but all the information I had gathered hadn't completely satisfied me. I had studied the Chart Supplement entry on the airport previously, and understood the basic layout and composition of the airport environment, as well as the services. Specifically, it was long and wide, with a small turn-out at one end. That it was rough gravel, and was unattended. This led me to believe that it was also unmaintained.

I decided to make a visual inspection of the runway as I passed by. I descended to approximately 200' AGL and passed to the right of runway 21, trying to gauge the snow cover. I was still flying at almost 100mph, which was my cruising speed in this aircraft. I saw a smooth, windblown snow cover, no drifts or ditches. The cones at either end of the runway were still visible, though it appeared to me they were smaller than the usual traffic cones. There were two or three marks on one end of the runway of an aircraft, or multiple aircraft +

The nose had dug into the snow, and the bottom engine cowling was dented, though the exhaust for the engine appeared to be in the normal orientation relative to the engine. No damage to the spinner, and the propeller was still straight, though with many scratches on the forward facing part of one blade. The right wing suffered a kink along the entire chord length, just inside of where the right strut meets the wing. Elsewhere on right wing I observed warped metal panels on the bottom side of the wing, primarily near the leading edge. The left wing suffered minimal visual damage. The flaps were almost completely in the raised position, though if they had been jarred during the crash, or the switch inside the cockpit had inadvertently been selected in the 'up' position while the battery was still running after the crash, I couldn't determine. The elevators were free of the snow and were still movable. The ailerons were also still movable, and the yoke moved correctly. The portion of the rudder visible above the snow had no damage and was still straight. The landing gear was intact with no visible damage. The cabin frame was not warped significantly, and I was able to open and close both passenger doors, as well as the cargo door. I do not recall if the ELT had activated. Some fluid eventually leaked from the engine compartment, though I did not investigate if it was fuel or just melted snow.

I had planned a solo flight for Monday, March 10, from Fairbanks to Talkeetna and back, to take advantage of the excellent weather over the Alaska Range. I began preflighting the aircraft around 10:20. During the preflight, I noticed the oil level was low, so I added 1 quart stored in the aircraft, per the club SOP. The oil was also scheduled to be replaced after my flight by the maintenance officer of the club. No other items were noted on the preflight. Afterward, I loaded the aircraft with two 8 gallon fuel bladders in the cargo area behind the rear passenger seat, the airplane engine blanket and personal survival equipment in the rear passenger seat, and my flight bag in the front passenger seat. Using Foreflight, I calculated my weight and balance, with a TOW of 2151 lbs, and a CG of 42 inches. With full fuel tanks I had more than enough fuel in the tanks for a flight to Talkeetna and back, but on long flights I liked to carry extra fuel in the bladders.

I did a final check of the weather along my route, also using Foreflight. I had already checked the weather using Foreflight the night before, and in the morning, so this was merely a final check that nothing along my route had changed dramatically. I was using my iPad running Foreflight, and a personal ADSB-In receiver which I use for airborne traffic alerts and to obtain in-flight weather information.

After getting the ATIS at Fairbanks, I was cleared to taxi from the East Ramp to 2R via Charlie. The runup proceeded normally, and I waited in the holding area at the end of taxiway Charlie for a few minutes extra to let the engine warm up a little bit more, as it had been a chilly morning. Takeoff was at approximately 11:00, and I was given a left hand turn on own navigation by departure, to avoid traffic to the southeast.

I gave ATC a heading of 212° for my initial heading, and leveled off at 3500' when departing the Class Delta. I held that course and altitude until I exited the TRSA. About 10 minutes after leaving the TRSA I turned to a heading of 193°, in order to 'cut the corner' of the Rex Dome and pass to the east of the dome in order to pick up the Parks Highway near Healy, instead of near Clear. As I approached the hills I gradually increased altitude to approximately 4000' to avoid some of the ridges between Rex Dome and Jumbo Dome. Around 11:40, I picked up the Parks Highway just south of the Healy airstrip (PAHV), and turned south to follow it, descending back down to around 2800'

I made one radio call on the Healy River CTAF as I passed the airstrip, and one more as I passed over the McKinley Park airstrip (PAIN), to no response. Using my ADSB I saw there was no traffic indicated, but I knew that non-ADSB or transponder equipped aircraft frequently fly at low level through the passes, so I maintained my visual scan of the pass ahead of me. I left the CTAF for the area on Radio 1, and I also tried to pick up the PAIN AWOS on 135.75 on Radio 2, but heard nothing. This meant I was still on the Fairbanks altimeter setting throughout the flight. I had planned on picking up the Talkeetna altimeter as far out as I could.

I passed through Windy gap with a slight descent to perhaps 1000' or 1200' AGL, monitoring the CTAF for traffic announcements. Between Cantwell airport (PATW) and Summit airport

(PAST), I noticed a double length semi-truck had run off into the ditch in the northbound lane of the Parks Highway. I quickly did a left-handed 180 to investigate and take pictures. As I came on to my original heading, roughly parallel to the highway southbound, I saw Summit airport just off my nose.

I had driven by Summit many times while on the highway, and had inquired about it from other pilots as an airstrip to base flying adventures in and around the mountains, but all the information I had gathered hadn't completely satisfied me. I had studied the Chart Supplement entry on the airport previously, and understood the basic layout and composition of the airport environment, as well as the services. Specifically, it was long and wide, with a small turn-out at one end. That it was rough gravel, and was unattended. This led me to believe that it was also unmaintained.

I decided to make a visual inspection of the runway as I passed by. I descended to approximately 200' AGL and passed to the right of runway 21, trying to gauge the snow cover. I was still flying at almost 100mph, which was my cruising speed in this aircraft. I saw a smooth, windblown snow cover, no drifts or ditches. The cones at either end of the runway were still visible, though it appeared to me they were smaller than the usual traffic cones. There were two or three marks on one end of the runway of an aircraft, or multiple aircraft, having done a touch and go. I saw three tracks per touch and go, which at the time looked like a tricycle gear aircraft. There was also a snow machine trail on the shoulder of the runway, running the length of the strip. None of these marks were particularly deep, perhaps a few inches, and there were no deep divots to otherwise indicated snow depth. At this point I appeared to me that the wind and warm weather had scoured much of the runway, so only a few inches of hardpack remained. As I passed the end of the runway 3, I decided to have a closer look. I made a left turn and entered a shallow traffic pattern for runway 21, intending to overfly the runway directly. While I was in the downwind I configured for slow flight, which included pulling back on the throttle and adding 20 degrees of flaps, slowing to approximately 80 mph. I turned base, then final, and began a shallow decent on final.

I was not intending to actually land on the strip at this point. I wasn't convinced that it was safe to land, but I also was not convinced that the snow was deeper than it turned out to be. Thus, I chose to descend to within 5-6 feet above the snow level to get an idea of what the surface looked like. I leveled off as I passed over the end of runway 21, intending to perform a low pass. I recall looking over my shoulder out the left-hand window at the snow, and noticed I was drifting lower. My main wheels touched the snow and immediately I felt the airspeed and the nose of my aircraft drop. I must have applied full power at that point, because my throttle knob was almost firewalled after the crash. However, my nosewheel must have already touched the snow because the airplane slowed further and I felt the airplane begin to tip. I recall the flipping motion, and engine noise cease abruptly. Then all the loose items in the cockpit fell to the ceiling, and I was hanging by my seatbelt. The attitude indicator had uncaged and was spinning. I was not pinned but was hampered by my flight bag that I had stored in the passenger seat, as well as papers and charts that had

been in the side pockets. While still upside down, I first turned off the fuel control, and the master switches. The ignition key was missing at this point. I unstrapped myself and exited the airplane from the passenger side door, which was the closest door to me after I had fallen to the ceiling.

The nose had dug into the snow, and the bottom engine cowling was dented, though the exhaust for the engine appeared to be in the normal orientation relative to the engine. No damage to the spinner, and the propeller was still straight, though with many scratches on the forward facing part of one blade. The right wing suffered a kink along the entire chord length, just inside of where the right strut meets the wing. Elsewhere on right wing I observed warped metal panels on the bottom side of the wing, primarily near the leading edge. The left wing suffered minimal visual damage. The flaps were almost completely in the raised position, though if they had been jarred during the crash, or the switch inside the cockpit had inadvertently been selected in the 'up' position while the battery was still running after the crash, I couldn't determine. The elevators were free of the snow and were still movable. The ailerons were also still movable, and the yoke moved correctly. The portion of the rudder visible above the snow had no damage and was still straight. The landing gear was intact with no visible damage. The cabin frame was not warped significantly, and I was able to open and close both passenger doors, as well as the cargo door. I do not recall if the ELT had activated. Some fluid eventually leaked from the engine compartment, though I did not investigate if it was fuel or just melted snow.

There was knee deep powder snow on the runway, under a crust of snow perhaps one inch thick. I had cell service and was able to initiate my own rescue and filing of the crash report. I removed from the airplane, but left beside it the two 8 gallon fuel bladders I had brought along in the cargo compartment. I took from the airplane my flight bag, survival equipment, the engine blanket I had placed in the backseat, the airworthiness certificate and registration, the keys I eventually recovered from the cockpit, as well as the fuel log stored in the plane. I attempted to close and lock both passenger doors. The crash itself took place at approximately noon, and I was picked up from the airport around 2:30pm.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

I would recommend not attempting such a low pass, and instead relying on conclusions from a higher runway inspection pass. In addition, assume from the Chart Supplement data that if the runway is remote and unmonitored, it is probably also unmaintained. It would also be recommended that the pilot use the highway berms nearby to determine the height of the snowpack, as well as any nearby outcropping of rock that was exposed to similar levels of wind and sun exposure to determine the amount of snow that could have possibly been removed by natural elements. It would also be recommended to examine any tracks on the runway, in order to determine what kind of plane could have landed there previously, and what kind of landing gear system that plane was equipped with.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/Cycles
On Part

_____ Hours

_____ Cycles

Time Since This Part
Inspected/Overhauled

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

48 Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

none

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Sole occupant, the pilot, unlatched from his seat while still upside down and exited through the passenger (right) side door.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

3/14/2025

mm/dd/yyyy

Name of Pilot/Operator: Dawson J Lewandoski

Dawson Lewandoski

Signature: 2025.03.14 11:42:38 -08'00'

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

ANC25LA023

Reviewed by NTSB Regional Office

AS-ANC

Name of Investigator

S. Joyce

Date Report Received

03/14/2025