



Mark Ward
Aviation Accident Investigator
AS-ANC

Date: 10/15/2025
Subject: ANC25LA1111 Pilot Statement
Contact: Brian Turner / Pilot

Summary of a phone conversation with Brian Turner. Brian stated that the accident happened during the landing roll out. The airplane landed on a hill and was in a high-power taxi to get to the top of the hill when the landing gear tire hit a pothole.