

Communication Summary

Date: March 12, 2012

Communication Included: Mr. Robert Warner



Summary & Factual Information from Conversation:

Mr. Warner was asked how the accident occurred and he answered that the airplane encountered a gust of wind. He was asked if there were any mechanical malfunctions with the airplane during the flight and he indicated that there were no mechanical issues.

I can attest that the above summary and factual information was taken on the above stated day, and is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator