



Photo 2 - Missing magnet as it is mounted on the transmission output yoke