



Photo 5 - The magnet was found affixed to a bolt just aft of the yoke, and a small dent was found on the horizontal firewall.