



MEMORANDUM OF RECORD

NTSB Accident Number: CEN14FA377

Location: Blackwell, Texas

Accident Date: July 20, 2014

According to the pilot's wife, Mrs. Patty Oden, the pilot said goodbye about 1000 to go to the airstrip. He mentioned to her that he was going to adjust the carburetor on the airplane's engine. Mrs. Oden became concerned when he didn't show at home and contacted the Texas Department of Public Safety (DPS) about 1822. A search by DPS located the wreckage about 2015.

Mrs. Oden's contact information is:

Mrs. Patty Oden

[REDACTED]

Blackwell, TX 79506

Phone: [REDACTED]

Dr. David Bowling

Regional Chief

NTSB, Central Region