

2:10PM airplane completed normal run up, rather long though. airplane departed runway 17, rotated about halfway down runway. plane reached estimated 100 - 200ft in altitude. aircraft took off with 0 Flaps, it didn't climb anymore. airplane went out of sight in a 10°-15° left bank. 2-3 minutes later the sound of the prop speeding up was heard, next was a impact sound. ~~then~~ 5 min later black smoke appeared. A STUDENT and I headed toward crash site. PARK RANGER was there also. airplane was consumed in fire, tail section was visible. Vacated scene, returned to HANGAR

8-16-2014

TYLER BARKER

~~_____~~

~~_____~~

~~_____~~