

Lindberg Joshua

From: [REDACTED] >
Sent: Monday, January 27, 2014 8:00 PM
To: Lindberg Joshua
Cc: [REDACTED]
Subject: 414CJ

Josh,

Just thought I'd send a quick summary of today.

It was cold!

Jim has the fuel totalizer and I told him that you would send a shipper when he has it ready.

We checked fuel samples pumped from the boost pumps for water with sar-gel. No water observed but whatever water in the fuel system was probably frozen and not pumped out.

Ice was observed in both engine fuel manifold valves and both airframe fuel strainers. We measured the chunk of ice from the left strainer bowl and it was about 1 3/8 inch thick. Ice was also noted in the wafer screens.

If you could let me know where you want pictures sent, I'll burn a disk tomorrow and send it. Also, the accident number and I'll get a party form to you.

Let me know if there is anything else.

Chris