

-----Original Message-----

From: Mike Council [REDACTED]

Sent: Wednesday, July 16, 2014 4:56 PM

To: Scott Arnold

Subject: Re: Engine Run IO-550-B6 s/n 675355

Arnold, the engine ran really well. We had to replace a couple of damaged induction pieces then it performed well. All it needed was fuel!

Mike

Sent from my iPhone

Mike Council

Continental Air Safety