

Yeager Leah

From: [REDACTED]
Sent: Thursday, May 08, 2014 10:24 AM
To: Yeager Leah
Subject: N7309Z Accident

Good Morning Lea,

I have inspected the aircraft and records and found no anomalies. I could not determine without tearing down the engine what caused it to loose power.

The engine will be shipped to Tulsa Aircraft Engines for teardown and repair, I think we could get a tear down report from them to determine the cause.

Their phone number is 918-838-3532.

If you have any other suggestions let me know. I will forward you an email with pictures of the damage to the aircraft.

If you need anything else, give me a call.

Dean O. Johnson
Primary Maintenance Inspector
Baton Rouge FSDO