


.....

Federal Aviation Administration

July 30, 2014

To Whom It May Concern:

The cog belt drive system was installed on 6/15/03 with 155.5 current time on aircraft hobbs meter. The cog belt drive system is to be inspected during each 25 hour standard inspection and the belt tension to be tested at each annual. There is no shelf life replacement time required, however the recommended replacement time is at 500 hours of use. The total time on the belt was 215.9 hrs. The belt was a Gates part number is 1792,62,8.



Sincerely,

Tim Payne

.....