

From: John Kent [REDACTED]
Sent: Thursday, October 30, 2014 11:02 AM
To: Scott Arnold
Subject: RE: Engine run

They just ran your engine to full power on the test stand. Metering unit had a small leak from impact damage.