

Memorandum for the Record – Pilot Telephone Summary

Accident Involving N878C – NTSB Case# CEN14LA480

August 6, 2014

---

Summary

The pilot stated that the airplane was applying herbicides to a milo crop field. As it passed over the field, the bottom of the airplane came into contact with the heads of the milo. The airplane continued through a six-strand wire fence and struck a metal post with the left wing, continued across a farm road and ground looped. The pilot exited the airplane and received medical treatment. The pilot reported no mechanical problems with the airplane prior to the accident.

---

Alex Lemishko

Senior Air Safety Investigator, NTSB