




Photo 8 - Severed Tail Boom and Vertical Stabilizer