

Air Methods	S/N:	N356AM	7006	S/N:	EngTT:	Fits	Strts	N1	N2	ICY	CCY	PCY	EXC
AIRFRAME	ACTT:	1378+40	ENG #1	46489	1378+40	4681		3,016.50	1,522.00				
COMPONENT/INSPECTION	Ldgs:	4681	ENG #2										

Bulletin

Task Code	Name	Part Number	Comp SN	Type	Remains	Due At	Notes
17-5302-EO-264	AD 2014-20-15 - 40 FH Repetitive Inspection of Tailboom / Fenestron Junction Frame (EASB 53A019, Rev. 1, 3.B.1, 3.B.3, and 3.B.4.).			Hours	18+28	1397+06	

Inspection

Task Code	Name	Part Number	Comp SN	Type	Remains	Due At	Notes
00C2622-01	30 Day Portable Fire Extinguisher Inspection	RT-A600	X-808647	Calendar	15	3/21/2015	
18A0500-04	A 0230 NT - 30 Hour MRB Inspection			Hours	17+39	1396+19	
18A0500-57	D 5090 - 30 Day Airframe Inspection			Calendar	9	3/15/2015	
18I0500-03	C 0130 - 25 Hour ICA Inspection			Hours	24+29	1403+09	
18I0500-14	C 1410 - 500 Hour ICA Inspection			Hours	17+44	1396+24	
27E0500-01	B 0090 NT - 15 Hour/7 Day Engine Inspection	0292005410	46489	Calendar	6	3/12/2015	
27E0500-01	B 0090 NT - 15 Hour/7 Day Engine Inspection	0292005410	46489	Hours	15+00	1393+40	
27E0500-09	B 0130 NT - 25 Hour Engine Inspection	0292005410	46489	Hours	24+29	1403+09	

Others

Task Code	Name	Part Number	Comp SN	Type	Remains	Due At	Notes
17-5302-EO-763 - Part 2	AD 2014-12-51 - Repetitive Check of the Forward Face of the tail boom / Fenestron junction frame from the inside.			Hours	21+23	1400+03	