

Name	ModeC	Name2	Mode3	Latitude	Longitude	F7
6:37:06 PM	5800	6000T	1200	31:53:59.00N	105:54:42.00W	QNW
6:39:54 PM	5900	6100T	1200	31:56:52.00N	105:58:02.01W	QNW
6:39:42 PM	5900	6100T	1200	31:56:53.00N	105:57:31.00W	QNW
6:39:30 PM	5900	6100T	1200	31:56:53.00N	105:57:01.01W	QNW
6:37:42 PM	6000	6200T	1200	31:54:55.00N	105:55:11.00W	QNW
6:37:54 PM	5900	6100T	1200	31:55:18.00N	105:55:20.01W	QNW
6:37:30 PM	6000	6200T	1200	31:54:37.00N	105:54:54.99W	QNW
6:37:18 PM	5900	6100T	1200	31:54:19.00N	105:54:40.00W	QNW
6:38:06 PM	5900	6100T	1200	31:55:38.00N	105:55:16.99W	QNW
6:33:06 PM	5600	5800T	1200	31:56:45.00N	105:55:14.00W	QNW
6:38:54 PM	5900	6100T	1200	31:56:47.00N	105:55:25.01W	QNW
6:33:30 PM	5700	5900T	1200	31:56:04.00N	105:54:49.99W	QNW
6:38:18 PM	5900	6100T	1200	31:55:56.00N	105:55:03.01W	QNW
6:33:42 PM	5700	5900T	1200	31:55:51.00N	105:54:40.00W	QNW
6:33:18 PM	5700	5900T	1200	31:56:22.00N	105:55:04.99W	QNW
6:38:30 PM	5900	6100T	1200	31:56:16.00N	105:54:59.99W	QNW
6:38:42 PM	5900	6100T	1200	31:56:32.00N	105:55:03.01W	QNW
6:39:18 PM	5900	6100T	1200	31:56:57.00N	105:56:24.01W	QNW
6:39:06 PM	5900	6100T	1200	31:56:57.00N	105:55:53.99W	QNW
6:32:54 PM	5600	5800T	1200	31:57:01.00N	105:55:16.99W	QNW
6:32:42 PM	5600	5800T	1200	31:57:31.00N	105:55:11.99W	QNW
6:32:30 PM	5600	5800T	1200	31:57:55.00N	105:55:02.00W	QNW
6:32:18 PM	5600	5800T	1200	31:58:14.00N	105:54:47.00W	QNW
6:36:18 PM	5800	6000T	1200	31:52:56.00N	105:53:38.99W	QNW
6:36:06 PM	5600	5800T	1200	31:52:48.00N	105:53:21.99W	QNW
6:36:42 PM	5800	6000T	1200	31:53:33.00N	105:54:10.00W	QNW
6:36:30 PM	5800	6000T	1200	31:53:14.00N	105:53:53.99W	QNW
6:36:54 PM	5800	6000T	1200	31:53:41.00N	105:54:27.00W	QNW
6:35:54 PM	5600	5800T	1200	31:52:47.00N	105:52:52.99W	QNW
6:35:42 PM	5500	5700T	1200	31:52:56.00N	105:52:24.01W	QNW
6:35:30 PM	5600	5800T	1200	31:53:17.00N	105:52:03.99W	QNW
6:35:18 PM	5600	5800T	1200	31:53:39.00N	105:52:13.00W	QNW
6:35:06 PM	5600	5800T	1200	31:54:01.00N	105:52:20.99W	QNW
6:34:18 PM	5700	5900T	1200	31:55:18.00N	105:53:33.01W	QNW
6:34:30 PM	5700	5900T	1200	31:55:03.00N	105:53:12.00W	QNW
6:33:54 PM	5800	6000T	1200	31:55:41.00N	105:54:10.99W	QNW
6:34:06 PM	5800	6000T	1200	31:55:36.00N	105:53:48.00W	QNW
6:34:54 PM	5600	5800T	1200	31:54:20.00N	105:52:35.99W	QNW
6:34:42 PM	5600	5800T	1200	31:54:49.00N	105:52:50.00W	QNW
6:32:06 PM	5600	5800T	1200	31:58:36.00N	105:54:25.00W	QNW
6:31:54 PM	5500	5700T	1200	31:58:47.00N	105:54:03.99W	QNW
6:31:42 PM	5500	5700T	1200	31:59:06.00N	105:53:30.01W	QNW
6:31:30 PM	5500	5700T	1200	31:59:24.00N	105:53:14.00W	QNW
6:31:18 PM	5500	5700T	1200	31:59:40.00N	105:52:46.01W	QNW
6:31:06 PM	5500	5700T	1200	31:59:58.00N	105:52:10.99W	QNW
6:30:54 PM	5500	5700T	1200	32:00:13.01N	105:51:43.01W	QNW

6:30:42 PM	5500 5700T	1200 32:00:31.00N	105:51:26.99W	QNW
6:30:30 PM	5600 5800T	1200 32:00:52.01N	105:51:02.99W	QNW
6:30:18 PM	5600 5800T	1200 32:01:13.00N	105:50:40.00W	QNW
6:30:06 PM	5600 5800T	1200 32:01:27.00N	105:50:11.00W	QNW
6:29:54 PM	5600 5800T	1200 32:01:48.00N	105:49:46.99W	QNW
6:29:42 PM	5600 5800T	1200 32:02:08.00N	105:49:22.00W	QNW
6:29:30 PM	5600 5800T	1200 32:02:22.00N	105:48:52.99W	QNW
6:29:18 PM	5500 5700T	1200 32:02:39.00N	105:48:35.99W	QNW
6:29:06 PM	5500 5700T	1200 32:02:52.99N	105:48:06.99W	QNW
6:28:42 PM	5600 5800T	1200 32:03:36.00N	105:47:09.01W	QNW
6:28:30 PM	5500 5700T	1200 32:03:53.01N	105:46:50.99W	QNW
6:28:18 PM	5500 5700T	1200 32:04:09.01N	105:46:33.00W	QNW
6:28:06 PM	5500 5700T	1200 32:04:29.00N	105:46:06.99W	QNW
6:27:54 PM	5500 5700T	1200 32:04:56.00N	105:45:44.99W	QNW
6:27:42 PM	5600 5800T	1200 32:05:15.01N	105:45:19.01W	QNW
6:27:30 PM	5600 5800T	1200 32:05:31.00N	105:45:00.00W	QNW
6:27:18 PM	5600 5800T	1200 32:05:51.00N	105:44:33.99W	QNW
6:27:06 PM	5500 5700T	1200 32:06:14.00N	105:44:18.00W	QNW
6:26:54 PM	5600 5800T	1200 32:06:32.99N	105:43:51.01W	QNW
6:26:42 PM	5600 5800T	1200 32:06:52.00N	105:43:24.01W	QNW
6:26:30 PM	5500 5700T	1200 32:07:15.00N	105:43:07.99W	QNW
6:26:18 PM	5500 5700T	1200 32:07:32.99N	105:42:41.00W	QNW
6:25:18 PM	5500 5700T	1200 32:09:08.00N	105:40:58.99W	QNW
6:25:06 PM	5500 5700T	1200 32:09:36.00N	105:40:26.00W	QNW
6:24:54 PM	5500 5700T	1200 32:09:52.00N	105:40:04.99W	QNW
6:21:55 PM	5500 5700T	1200 32:14:40.99N	105:33:49.01W	QNW
6:21:43 PM	5500 5700T	1200 32:14:57.01N	105:33:17.01W	QNW
6:21:31 PM	5500 5700T	1200 32:15:18.00N	105:32:56.00W	QNW
6:21:19 PM	5500 5700T	1200 32:15:42.00N	105:32:26.01W	QNW
6:20:55 PM	5600 5800T	1200 32:16:18.00N	105:31:32.01W	QNW
6:20:43 PM	5600 5800T	1200 32:16:39.00N	105:31:11.00W	QNW
6:20:31 PM	5600 5800T	1200 32:16:52.01N	105:30:46.01W	QNW
6:20:19 PM	5600 5800T	1200 32:17:14.99N	105:30:16.01W	QNW
6:20:07 PM	5600 5800T	1200 32:17:35.00N	105:29:53.00W	QNW
6:19:55 PM	5500 5700T	1200 32:17:47.99N	105:29:28.99W	QNW
6:19:43 PM	5500 5700T	1200 32:18:11.00N	105:28:56.99W	QNW
6:19:31 PM	5500 5700T	1200 32:18:31.01N	105:28:34.00W	QNW
6:19:19 PM	5500 5700T	1200 32:18:45.00N	105:28:00.00W	QNW
6:19:07 PM	5500 5700T	1200 32:19:05.00N	105:27:37.01W	QNW
6:18:55 PM	5500 5700T	1200 32:19:27.00N	105:27:04.99W	QNW
6:18:43 PM	5500 5700T	1200 32:19:47.00N	105:26:41.01W	QNW
6:18:31 PM	5600 5800T	1200 32:20:01.00N	105:26:05.99W	QNW
6:18:19 PM	5600 5800T	1200 32:20:21.01N	105:25:42.01W	QNW
6:18:07 PM	5600 5800T	1200 32:20:42.00N	105:25:09.00W	QNW
6:17:55 PM	5600 5800T	1200 32:21:02.00N	105:24:44.99W	QNW
6:17:43 PM	5700 5900T	1200 32:21:21.99N	105:24:10.99W	QNW
6:17:31 PM	5800 6000T	1200 32:21:42.00N	105:23:46.00W	QNW

6:17:19 PM	5800 6000T	1200 32:22:14.00N	105:23:33.01W	QNW
6:17:07 PM	5800 6000T	1200 32:22:41.00N	105:23:09.99W	QNW
6:16:55 PM	5800 6000T	1200 32:22:58.00N	105:22:54.01W	QNW
6:16:43 PM	5800 6000T	1200 32:23:16.99N	105:22:28.00W	QNW
6:16:31 PM	5800 6000T	1200 32:23:30.00N	105:21:51.99W	QNW
6:16:19 PM	5800 6000T	1200 32:23:41.00N	105:21:24.00W	QNW
6:16:07 PM	5800 6000T	1200 32:24:00.01N	105:20:57.99W	QNW
6:15:55 PM	5800 6000T	1200 32:24:11.01N	105:20:30.00W	QNW
6:15:43 PM	5800 6000T	1200 32:24:22.01N	105:20:03.00W	QNW
6:15:31 PM	5800 6000T	1200 32:24:27.00N	105:19:24.00W	QNW
6:15:19 PM	5800 6000T	1200 32:24:44.99N	105:18:57.00W	QNW
6:15:07 PM	5800 6000T	1200 32:25:09.00N	105:18:40.99W	QNW
6:14:55 PM	5800 6000T	1200 32:25:33.00N	105:18:35.00W	QNW
6:14:43 PM	5800 6000T	1200 32:26:05.00N	105:18:20.01W	QNW
6:14:31 PM	5800 6000T	1200 32:26:30.00N	105:17:53.01W	QNW
6:14:19 PM	5800 6000T	1200 32:26:55.00N	105:17:36.99W	QNW
6:14:07 PM	5800 6000T	1200 32:27:12.99N	105:17:09.01W	QNW
6:13:55 PM	5700 5900T	1200 32:27:29.01N	105:16:50.99W	QNW
6:13:43 PM	5700 5900T	1200 32:27:40.01N	105:16:11.99W	QNW
6:13:31 PM	5700 5900T	1200 32:27:51.01N	105:15:42.00W	QNW
6:13:19 PM	5700 5900T	1200 32:28:00.00N	105:15:12.99W	QNW
6:13:07 PM	5800 6000T	1200 32:28:10.00N	105:14:43.99W	QNW
6:12:55 PM	5800 6000T	1200 32:28:18.99N	105:14:23.99W	QNW
6:12:43 PM	5800 6000T	1200 32:28:29.99N	105:13:34.00W	QNW
6:12:31 PM	5800 6000T	1200 32:28:40.01N	105:13:05.00W	QNW
6:12:19 PM	5800 6000T	1200 32:28:56.00N	105:12:35.01W	QNW
6:12:07 PM	5800 6000T	1200 32:28:58.00N	105:12:04.99W	QNW
6:11:55 PM	5800 6000T	1200 32:29:15.00N	105:11:35.00W	QNW
6:11:43 PM	5800 6000T	1200 32:29:24.01N	105:11:05.00W	QNW
6:11:31 PM	5800 6000T	1200 32:29:40.00N	105:10:36.00W	QNW
6:11:19 PM	5900 6100T	1200 32:30:11.00N	105:10:16.99W	QNW
6:11:07 PM	6000 6200T	1200 32:30:34.00N	105:10:08.01W	QNW
6:10:55 PM	6000 6200T	1200 32:31:04.00N	105:10:09.00W	QNW
6:10:31 PM	6100 6300T	1200 32:32:03.99N	105:10:23.01W	QNW
6:10:19 PM	6100 6300T	1200 32:32:33.00N	105:10:35.01W	QNW
6:10:07 PM	6100 6300T	1200 32:32:56.00N	105:10:36.00W	QNW
6:09:31 PM	6100 6300T	1200 32:34:25.00N	105:10:52.01W	QNW
6:09:19 PM	6100 6300T	1200 32:34:49.00N	105:10:31.99W	QNW
6:09:07 PM	6100 6300T	1200 32:35:19.00N	105:10:33.99W	QNW
6:08:55 PM	6100 6300T	1200 32:35:48.99N	105:10:24.00W	QNW
6:08:43 PM	6000 6200T	1200 32:36:10.99N	105:10:36.00W	QNW
6:08:19 PM	6100 6300T	1200 32:36:57.00N	105:10:06.01W	QNW
6:08:07 PM	6000 6200T	1200 32:37:05.99N	105:09:44.01W	QNW
