



HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-E4N-3/E9083SK

PROPELLER S/N HH 3648

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model HC-E4N-3

High/Feather 86.0

Propeller S/N HH 3648

Start Lock _____

Blade Design E 90835K

Low 21.0

Blade S/N's

Reverse -11.0

No. 1 K 84991

No. 2 K 85001

Aircraft Manufacturer _____

No. 3 K 85000

Aircraft Model _____

No. 4 K 84996

S/N _____

No. 5 _____

Registration _____

No. 6 _____

Spinner Assembly Part No. _____

Propeller

Columbia Air Services, Inc. LOG BOOK ENTRY

Page 1 of 1

A/C REG: N425KJ

A/C S/N: 518

DATE: 12/29/14

A/C TOTAL TIME: 656.7

HOUR METER: 656.7

W/O NO: MWO-14-4729

ENGINE TOTAL TIME 656.7

S.M.O.H.

1. Complied with an A+ Inspection per Socata TBM 850 Model Maintenance Manual chapter 5-20-02. Researched AD's through Bi-Weekly 2014-26.
2. Complied with the following special checks:
 - ✕ 1 year propeller assembly inspection.
 - ✕ 400/1 year propeller lubrication.
 - ✕ 600/1 year beta ring and carbon block dimensional check.
3. Dressed and painted propeller blades as required.
4. Performed post inspection ground run and aircraft flight check. Operational and leak checks satisfactory.

-----END-----

Columbia Air Services, Inc.

GROTON-NEW LONDON AIRPORT
GROTON, CONNECTICUT 06340

FAA Repair Station #SO5R204N. Work Order # MWO-14-4729

I certify that this **Propeller** has been inspected in accordance with an **A+** Inspection per Socata TBM 850 Model M.M. chapter 5-20-02, and determined to be in airworthy condition. Pertinent details of the inspection are on file at this facility.

Date: 12/29/14 A/C Total Time: 656.7

Signature: 