

NATIONAL TRANSPORTATION SAFETY BOARD

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ►

ACCIDENT NUMBER:

CEN15FA422

For Use In All Modal Investigations

REGISTERED OWNER (name and address) CASEY J BUSSETT [REDACTED] YUKON, OK 73099		IDENTIFICATION NUMBER N929DS	
		MAKE PIERCE, HENRY	
LOCATION GRANBURY, TX	DATE OF ACCIDENT 9/24/15	MODEL BUSHBY MUSTANG II	
RETAINED BY NTSB REPRESENTATIVE Thomas J. Latson, Jr.		TITLE Air Safety Investigator	DATE 9/25/15
The National Transportation Safety Board has ☐ has not ☒ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released. ☐ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE Thomas J. Latson, Jr.		TITLE Air Safety Investigator	DATE 10/7/15
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.) I HEREBY ACKNOWLEDGE: ☒ Receipt of the above described wreckage. ☒ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT [REDACTED] Heidi D. Vicknair		TITLE Attorney	DATE 3/2/16
ADDRESS [REDACTED] Houston, TX 77036		PHONE NUMBER & EMAIL [REDACTED]	
REMARKS: The NTSB had previously retained a slightly damaged GoPro video camera which was recovered from the cockpit of N929DS. The GoPro camera will be returned to the registered owner after the NTSB's final aircraft accident report is published. The NTSB had previously retained six burned and badly damaged cockpit avionic devices. The examination of those devices has been completed and they were returned to storage with the rest of the wreckage of N929DS. Storage or disposal of the wreckage is at the discretion of the registered owner. Except for the GoPro video camera, ALL other wreckage of N929DS is finally released to the registered owner.			