



NATIONAL TRANSPORTATION SAFETY BOARD

Record of Conversation

Person Interviewed: Richard Ball, Lone Star Retrieval

Subject: – CEN15LA018

Mr. Ball stated that the crew that recovered N550AC was aware that the #3 cylinder intake rocker-cover was missing from the engine. While recovering the aircraft, they looked for the cover but never located it.

Leah D. Yeager
National Transportation Safety Board
Senior Air Safety Investigator