



Photo 1 - Ice build-up on outboard of horizontal and elevator tip



Photo 2 - Spinner – Frost and Ice buildup