

RECORD  
91.409

INSPECTION RECORD  
F.A.R. 43.11-91.409

INSPECTION-STATUS & DISCREPANCY LIST  
PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE

DATE

AIRCRAFT TIME  
IN SERVICE

KIND OF INSPECTION-STATUS & DISCREPANCY LIST  
SIGNATURE — CERT. NO. OF PERSON APPROVING OR DISAPPROVING AIRCRAFT FOR SERVICE

2 CHANGE. REPLACED ENGINE HTR FAN  
1 PER 912092 FOR OPS. OK. BATTERY DUE  
IS ON FAN SHROUD COVER. AO'S CURRENT  
CERTIFY THIS AIRCRAFT HAS BEEN  
INSPECTION WITH A 100 HR INSPECTION  
TO BE IN AIRWORTHY CONDITION.

AP

RPM HORN P. N. B-320-3 28V WITH  
2D. REPLACED BEACON STROBE POWER  
7062-03 REV R WITH NEW UNITS.  
TURN TO SERVICE.

AP

10-7-2014 ROBINSON R 44 II N444KD SN 10166 HOBBS 494.7 ACTT 3186.6  
ACSOH 963.2 Repaired cracks in left and right side engine cowl.  
Replaced loose rivets aft support panel on tail cowl. New fwd yoke  
rod ends on swashplate. New bushings and bolts in swashplate  
swivel links. New fwd cross tube bellows cover, New fuel cap seals.  
New gascolator screen and bowl gasket.

10-7-2014 ROBINSON R44 11 N444KD SN 10166 HOBBS 494.7 ACTT 3186.6  
ACSOH 963.2 I certify that this aircraft has been inspected in accordance  
with an annual inspection and determined to be in an airworthy condition.